

Great Lakes Water Quality Laboratory, Inc.
P.O. Box 131
Lake Ann, MI 49650
231-275-7382

Hamlin Lake									
Results Report									
		July 20, 2011	July 21, 2010	July 28, 2009	August 5, 2008	August 15, 2007	August 18, 2006	August 3, 2005	July 21, 2004
NO	Collection Site	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml
1	Narrows	2.0	<1	1	2	1.0	57	0	1
2	Dunes North	3.0	<1	11	16	1.0	37	0	2
3	Dunes Middle	8.6	<1	41	1	0.0	10	1	0
4	Dunes South	3.1	<1	8.6	8.6	0	2	3	3
5	Entrance to State Park	<1	<1	0	<1	0	0	0	0
6	Piney Ridge North	1.0	4.0	0	1	3.1	0	1	0
7	Piney Ridge South	8.5	<1	0	<1	0	0	0	1
8	Tamarac	13.1	36.8	7.4	9.9	12.0	5	3	2
9	South Bayou	30.5	48.7	15.8	8.6	7.5	33	1	2
10	Middle Bayou	7.5	5.2	4.1	9.8	3.0	12	0	7
11	North of Halls Shoreline	5.2	4.1	3.1	1	0	0	0	0
12	North Bayou	<1	2.0	2	4.1	0	24	0	2
13	Partridge Point swimming area	8.5	5.2	7.5	2	0	13	3	0
14	Lower Lake--east of deep hole	2.0	<1	5.2	2	1.0	0	0	3
15	Sunset Bay	2.0	<1	0	1	1.0	27	0	1
16	Outlet to Indian Pete	2.0	2.0	0	4.1	1.0	0	0	0
17	Indian Pete--Outlet to east bayou	1.0	<1	0	5.2	4.1	214	2	15
18	Barnhardts	1.0	3.1	1	8.6	0	2	0	0
19	Wilson Hill	12.1	<1	1	3.1	0	0	4	0
20	Layman's landing	4.1	2.0	2	1	4.1	0	26	0
21	Victory Park	8.5	3.1	1	4.1	6.3	370	36	1
22	Upper Reaches, Near swans	107.1	9.6	10.9	18.9	57.3	4	8	68
23	Malliet Bayou	18.9	9.6	3.1	6.3	2.0	0	8	0
24	North Shore-East of Babcock	8.6	<1	3.1	1	0	1	0	0
25	Rupert Bayou--Gartside	2.0	<1	0	1	0	0	10	0